PAT-NO:

JP359189613A

DOCUMENT-IDENTIFIER: JP 59189613 A

TITLE:

IGNITION COIL FOR INTERNAL-COMBUSTION ENGINE

PUBN-DATE:

October 27, 1984

INVENTOR-INFORMATION:

NAME

HASE, YUKIO

ASSIGNEE-INFORMATION:

NAME

COUNTRY

NIPPON DENSO CO LTD

N/A

APPL-NO:

JP58066235

APPL-DATE:

April 13, 1983

INT-CL (IPC): H01F031/00, H01F027/32

US-CL-CURRENT: 323/360, 505/870

ABSTRACT:

PURPOSE: To improve the heat discharge to the fitting part and reduce the temperature of the whole coil and improve the quality by making the winding density of the center portion of the primary coil lower than that of the both side portions of the coil.

CONSTITUTION: A core 1 is composed of laminated rectangular silicon-steel plates. Holes 2, with which the core 1 is fitted to a body, are provided to both ends of the core 1 and the core 1 is tightened and fitted to the fitting

BEST AVAILABLE COPY

part of the body frame or the like by bolts. The core 2 is not only a core but also has a function of discharging the heat generated by the primary coil to the body frame. When the **core** is not fitted to the body, the temperature is higher than that when the **core** is fitted by 40∼60°C. The primary **bobbin**

4, which is made of resin and molded after the **core** 1 is inserted, is divided into three winding ditches by rims 5a, 5b. For instance, 85∼95% of the whole winding of the primary coil 3 wound in the bobbin 4 is wound in the two ditches at the both ends and 5∼15% of the whole winding is wound in the center ditch. An insulation means such as insulating paper can be used as a substitute for the primary bobbin 4.

COPYRIGHT: (C)1984,JPO&Japio

⑬ 日本国特許庁 (JP)

①特許出願公開

[®] 公開特許公報(A)^{*}

昭59-189613

①Int. Cl.³H 01 F 31/00 27/32 做別記号

庁内整理番号 6969—5至 8323—5至 **國公開 昭和59年(1984)10月27日**

発明の数 1 審査請求 未請求

(全 3 頁)

❷内燃機関用点火コイル

御特

顧 昭58-66235

②出 票 昭58(1983)4月13日

肉発 明 者 長谷 基雄

刈谷市昭和町1丁目1番地日本 電装株式会社内

⑩出 願 人 日本電装株式会社

刈谷市昭和町1丁目1番地

⑩代 理 人 弁理士 岡部隆

男 和 似

1. 宛图の名称

内盤瞬間用点火コイル

2. 特許鮮水の箱腔

コアの開催を事体等の取付部に取付固定する内 機機開用点火コイルにおいて、前記スプの外間に 健けた一次ポピン又は始盤都等の絶縁学数と、数 独録学数に名かれた一次コイルと老値点、この一 次コイルの中央部の機械器度を同婚郎の機能密度 より少なくした内螺機器用点火コイル。

3. 発明の斜板な影明

本発明は内燃姆間用点火コイルの破棄を及に調するもので、一次コイルの基準達を改良することにより、コイル発熱温度を下げ、時命を向上させるものである。

従来用知のパッテリー点火コイルは、ロア、良いは、一次ボビンの上に、宣告 0.8 m程度のコイルを、3~4 間の範囲で、約400回程度皆念していた。その為、進電により、コイル中心部の発展が貫かった。

せこで、本発明は一次コイル中心部の観度を下げると同時に、コイル全体の温度も下げようとするものであり、一次コイル中心的の樹飲を練らし、阿錦の陶散を多くとることにより、まずコイルの新は島ははにより、コアを通り、コアの実機取付孔よりははいい、ガラ南端のコイル総数を多くさることにより、既放散量が増えて、全体の温度を下げることができることを置的とする。

以下本売到を図に乗す実施的について説明する。 馬1図において、1は長方形の企業解析を機関してなるコフで、開始に単体へ取付けるための孔 2 があいており、図示しないボルトにて車体フレーム等の取付部に制付図定される。なお、コア 2 は 低心であると共に、一次コイルの強烈を車体フレームに放動する機能もあり、単体フレームへ取付 けた場合に対し、取付けない場合は 4 0 で~ 6 0 でも温度が高くなる。 4 はコフ1をインサート成 形してなる明確製の一次ボビンで、ツバ5 4、5 りにより3つの名称に分割されている。 3 は前記 ポピン4 に参かれた一次スイルで、同時の色額に 金融数の B 5 ~ 9 5 気が通付けてあり、中心の磁 架に 5 ~ 1 5 光通付けてある。

第2回はコイルの勘線構造を変えた場合のコイ ル各部の温度を載わした特性園で、従来の様に一 つの恩罪に全船敷を密密する楊毓様迎では、実施 で示すごとく、中央部で205℃、関略的で19 Q でであるのに対し、第1 図に示す様な分割低に したものでは、破職で示すごとく中央師で180 で、可強郎で185セと下がっており、ピーク弘 皮は208でから185℃と20℃も低下し、第 5 図に来す、地鉄用電脑の熱寿命特性圏(促性ボ リエステルッイヤーの温度ー舞会時間特性図)か らも分るように、205七0資命700時間に対 と185℃の寿命30D0時間と約4倍に丹命を 律はすことができる。また、一次スイルろの温度 が低下するととにより、一次コイル8の外間に巻 かれる因示しない、二枚コイルの根底も下げるこ とができ、コイル全体の舞台を伸ばし、品質向上

四、第3四社告試用電線の協再会特性関である。 1…コア、2…取付孔、3…一次コイル、4… 一次ポピン。

化催入异理士 跖 郎 唯


かできる。

なお、上述した実施例においては、一次ポピン 4 モッパ 5 a、 5 b により格勝を3 つに分割した が、増額の別れがなければ、ツバ 5 a、 5 b を表 止しても阿珠の幼弟が得られる。また、一次ポピ ンもの代わりに継続紙等の絶縁手段を用いること もできる。

以上述べたように本発明においては、一次コイルの動態を開始に多く他色、中心部を少なくしたととにより、最高発熱部が単体フレーム等の取付部に近くなり、取付部への飲料が良くなり、全体のコイル程度が低下するので発動再分が伸び品質が低下する。また、塩味労命が種間品質の場合は、電味の財料ランクを19ンク下げてコストグランを計ることもできる。その上、一次ボビン等の地様子取の材質も品質的に向上することができるという優れた効果がある。

4. 図面の前単な税明

第1四は半発明コイルの一覧施例を示す要報の 銀斯顧図、第2回は第1回図示コイルの総度特性



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

□ BLACK BORDERS
□ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
□ FADED TEXT OR DRAWING
□ BLURRED OR ILLEGIBLE TEXT OR DRAWING
□ SKEWED/SLANTED IMAGES
□ COLOR OR BLACK AND WHITE PHOTOGRAPHS
□ GRAY SCALE DOCUMENTS
□ LINES OR MARKS ON ORIGINAL DOCUMENT
□ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.